Part-II

(To be filled by S.D.E of P.W.D B&R Department) <u>Building Safety Report</u>

Name of School: - SACRED HEART SR. SEC. SCHOOL, B.R. S. NGR. LDH.

I have visited the above mentioned School building along with Sh.

on dated 1/1/2023 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a. Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in Charge for Construction are not available.
- b. In case of any addition, alteration of expansion and modification of this building are done; certificate may be re-obtained after completion from undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d. A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e. A separate certificate regard Electrical Work should be obtained from the competent authority.
- f. The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report.
- g. The covered area of the building is 309671.27 Sel
- h. This report is not valid for legal purpose.

Junior Engineer

Endst. No. 597

Provincial Sub Liviation No. 3.
P.W.D. B&R, Br. LUDHIANA.

Copy forwarded to the Principal Sacred Heart Sr. Sec. School, B.R.S Nagar, Ludhiana

for further necessary disposal. No additional/alteration or expansion for modification to this

Principal building is to be carried out without permission of the undersigned.

Sacred Heart Sen. Sec. School Bhai Randhir Singh Nagar

Ludhiana

acred Heart Sr. Sec., School

Provincial Division